

Phone : 4262326, 4262416, 4262518, 4262923, 4111119
Facsimile : (977)-1-4262516
e-mail : cnsatm@mos.com.np
Cable : AIRCIVIL
AFTN : VNKTYAYX



CIVIL AVIATION AUTHORITY OF NEPAL

Head Office, Babar Mahal, Kathmandu, Nepal

Ref. No.: FOS 072/78

Flight Safety Standards Department

Date:

CHA No. 1336

Circular No. 6

24th April 2016

To,
Training Department,

Nepal Airlines Corporation, Kantipath

VVIP Flight, TIA, Gauchar

Buddha Air Pvt. Ltd., TIA, Gauchar

Tara Air Pvt. Ltd., Tilganga

Sita Air Pvt. Ltd., Sinamangal

Simrik Airlines Pvt. Ltd., Minbhawan

Goma Air Pvt. Ltd., Dhumbarahi

Yeti Airlines Pvt. Ltd., Tilganga

Air Kasthamandap Pvt. Ltd. Baluwatar

Makalu Air Pvt. Ltd., Baluwatar

Saurya Airlines Pvt. Ltd., New Baneshwor

Himalaya Airlines Pvt. Ltd., Gairidhara

Air Dynasty Heli Service, Sinamangal

Fishtail Air Pvt. Ltd., Tinkune

Simrik Air Pvt. Ltd., Tinkune

Mountain Helicopters Pvt. Ltd. Sinamangal

Shree Airlines Pvt. Ltd, Tripureswor

Manang Air Pvt. Ltd., Sinamangal

Prabhu Helicopter Pvt. Ltd., Sinamangal

Subject: IP Training

Reference to the meeting of 15th March 2016 and 22nd April 2016, you are required to provide your feedback on the following questions within seven working days:

1. Does your Type manufacturer have its own ATO?
2. If your manufacturer has its own ATO, does it provide Type Rating Instructor training?
3. If such a requirement was put in place by CAAN how long would you take to be ready to implements this requirement?
4. Do you know of any status that has applied this type of requirement?
5. Do you have an alternate means of complying with this requirement should it be implemented?

Capt. Deepak Kr. Lama
Manager
Flight Operations Section

C.C.

Deputy Director General (DDG), 2sir for your kind information
CAAN Head office Babarmahal

FSLD, FSSD, Sinamangal

OIC