



**Civil Aviation Authority of Nepal**  
**Aviation Safety Department**

Sinamangal, Kathmandu, Nepal

178

4111075  
4111042  
4111119

Fax: 977-1-4111198

P.O.Box: 6929

E-mail: asdnepal@wlink.com.np

Ref. No.: AW/121/066167

Date: 1<sup>st</sup> December, 2009

QA Chief  
Sita Air Pvt Ltd  
Kathmandu, Nepal

QA Chief  
Agni Air Pvt Ltd  
Kathmandu, Nepal

QA Chief  
Tara Air Pvt Ltd  
Kathmandu, Nepal

**Subject: - Booster Pump operation requirement in MEL.**

As per decision dated 11/8/2066, all Dornier operators are hereby informed to revise to revise their existing MEL Chapter 28 involving Booster Pump operation. Repaired Category should be in Category A, means with one Booster Pump inoperative, aircraft can Fly only up to base, meeting the respective PHO requirements. All operators are hereby therefore requested to revise the effected chapter and Item of their existing MEL and get it approval from CAAN within seven days.

*P.C. Mallik*

P.C. Mallik  
Airworthiness Engineer  
Airworthiness Inspection Division