



Ref. No.: - AW/113/063/64

Civil Aviation Authority of Nepal  
**Aviation Safety Department**

Sinamangal, Kathmandu, Nepal



1210  
: 4486775, 4467342  
: 4471933, Ext. 2515, 2516  
Fax : 977-1-4472998  
P.O. Box: 6929  
E-mail : atsc@ccsl.com.np

September 26, 2006

Sub: Main Frame Inspection of DO-228

**URGENT NOTICE TO ALL DORNIER 228  
OPERATOR**

You are required to check main frame # 18 and #19 of DO-228 in accordance with DO-228 Inspection Program and send a report to airworthiness inspection division urgently. You are requested to inform CAAN Airworthiness Inspector regarding your inspection time for surveillance.

B.R. Subedi  
Sr Officer  
Airworthiness Inspection Division.

CC: Director, Aviation Safety Department Sir for your kind information.