



Civil Aviation Authority of Nepal
Flight Safety Standards Department
Sinamangal, Kathmandu, Nepal

4111075
4111042
4111119

Fax: 977-1-4111198

P.O. Box: 6929

E-mail: asdnepal@wlink.com.np

Ref. NW/362/069/70



218

Date: 25th March, 2013

Air Kasthmandap

Makalu Air

Goma Air

Sub: Inspection on Critical Areas

You are requested to carry out visual inspection on critically stressed areas which includes landing gears attachment fittings, wing to fuselage attachment fittings and other areas as applicable within 3 days and submit the certified report on the inspection from an authorized AMT for your aircrafts.

Yours Sincerely

Er. Bidhan Shrestha
Sr. Officer
Airworthiness Inspection Division

O/c